

Power Quality Improvement Services Ltd 6-8 School Lane Standish WN6 0TD

Tel: 01257 434218


enquiries@pqis.co.uk www.pqis.co.uk

Power Factor Correction Explained

Good power quality


The graph illustrates a good power quality. The reactive power (KVAR) is low and the maximum demand (KVA) is close to the consumption (KW). The power factor of the supply is consistently 0.98.





Good Power Factor

The difference between the good and bad power quality achieved in the graphs on pages 1 and 2 is the power factor of the supplies. Power factor is a value from **0.00** to **1.00**, a power factor below is considered poor and efficiency improvements can be made.






Power Quality Improvement Services Ltd 6-8 School Lane Standish WN6 0TD

Tel: 01257 434218

enquiries@pqis.co.uk www.pqis.co.uk


Bad power Quality

A supply with a low power factor has a high reactive power (KVAR) which inflates the maximum demand (KVA) higher than the consumption (KW). The power factor achieved for this supply is consistently less than **0.85**



Low Power Factor

A low power factor is caused by the connection of inductive loads i.e. motors to an electricity supply.



Power Factor Correction

To improve the power factor of an electrical system a power factor correction unit is installed. A correctly specified power factor correction unit will achieve a consistent power factor of 0.98.

A good power factor reduces reactive power (KVAR), maximum demand (KVA) and system losses (KW) of an LV electricity supply. This increases capacity of the system and reduces electricity costs.